



Certificate Number: BB2671250-X

ABS Port Office: Bilbao

Date: 18-July-2014

Service Provider's address: Muelle del Rendiello, s/n Buzon 44, 33212 Puerto de El Musel, Gijon, Spain

Service Provider's Web Site www.seasubservices.com

Unless cancelled earlier, this certificate expires on 18 July 2017

For particulars regarding this recognition, see the ABS web site: www.eagle.org

Certificate of Service Recognition

This is to Certify that

Tecnicas Submarinas, S.L.

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

In Water Survey

It is the responsibility of the Service Provider to employ, train and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo Identification and, if allowed, be listed on the company's web site (noted above). The products and models allowed to be serviced are to be listed on the company's web site. The ABS office issuing this certificate to be kept updated with changes to the management of the company, its employees, products and models on the list and any changes made.

Note: Please refer to the ABS web site; www.eagle.org for any comments regarding the services provided.

Service Recognition Survey of ship's underwater structure, bearing clearances measurement, corrosion damages, structural deformation, .


Martinez Illoro, Arturo P. , Surveyor

